

Technical Bulletin

EOF005 Advice

Advice on Oil Filter EOF005



FIRST FOR
FILTERS

Some users are reporting an oil light issue when filter part number EOF005 is installed in vehicles with a 1.2VTI (PSA) engine. Below are two solutions to rectify this issue.

- 1** Fill the filter with oil prior to installation to avoid the issue. This should be **grade 0W30**.
- 2** If the oil light issue occurs after an oil change and first engine start, loosen the filter to release the air lock and re-tighten before the next engine start to solve the issue.

